



Metallic Gem

Design courtesy of Slumpy's


Hello gorgeous! Use our Earrings and Jewelry Fusing Pod Mold and a touch of dichroic accents to create a one of a kind piece of jewelry!

MATERIALS

Assorted Fine Carolina Frit
GCU-100-I-SRL Clear Iridescent Spiral Cut-Ups
DG-USC-96-NDL Rainbow Clear Noodles - Dichroic Glass
SM-7022 Earrings and Pendant Fusing Pod Mold
SP-8268 GlasTac Gel
SP-8302 Bead & Jewelry Tips w/ E6000 Adhesive Package
SP-9163 Gold Plated Jewelry Bails - Medium
ST-205 Boron Nitride Spray II
ST-356 Tarheel Tools Wheeled Mosaic Nipper

SUPPLIES

Angled Cut Straw
Toothpick



INSTRUCTIONS

1. Prime the Earrings and Pendant Fusing Pod Mold with Boron Nitride Spray prior to use.
 2. Choose two complimentary colors of transparent fine Carolina Frit.
 3. Using an angled cut straw as a small spoon to dispense your frit, create concentric teardrop shapes rings within the teardrop-shaped pendant shape on the fusing mold, alternating between the frit colors. Set aside.
- TIP: When filling the pendant shape, add each concentric ring of frit layer by layer at a time to avoid mixing. Repeat until you fill the pendant shape to the brim.
4. Use a Tarheel Tools Wheeled Mosaic Nipper to nip Rainbow Clear Dichroic Noodles into smaller, square-shaped pieces.
 5. Use pinpoint of GlasTac to attach the cut Dichroic Noodle pieces to the surface of the Clear Iridescent Spiral Cut-Up. Let dry,
 6. Position the Spiral Cut-up onto the filled pendant shape, near the larger bottom half.
 7. Carefully transfer the fusing pod mold to the kiln and full fuse using the 6-segment firing schedule.
 8. Once fired, use E-6000 Jewelry and Bead glue to attach a medium-sized jewelry bail to the top point of the pendant. Let dry.
 9. Complete your pendant necklace by adding string, cord, or a chain to the bail.